


X Threaded Rod



1	GT Cable 6
2	M4 x 5 Grub Screw
3	40 Tooth 3M Gear
4	M3 x 4 Grub Screw
5	20 Tooth 3M Gear
6	M6 x 42 Hex Bolt [6]
7	BK12 Block
8	X-Gantry Motor Mount
9	M5 x 8 Hex Bolt [2]
10	M5 x 32 Hex Bolt [4]
11	M5 x 11 Hex Bolts [4]
12	Nema Stepper 57BYGH627
13	Limit Switch 7397K21 [2]
14	1610 Ball Screw 693mm
15	BF12 Block
16	X-Gantry Endstop Block